


This report provided free of charge by:

Canyon State Classics LLC


2613 W Birchwood Cir 7 Mesa, AZ 85202

888-378-5093





This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 11/24/25 at 7:02:23 AM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.





Summary

Total Loss No total loss reported to CARFAX.	No Issues Reported
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	No Issues Reported
Odometer Check No indication of an odometer rollback.	No Issues Indicated
Accident / Damage Accident reported: 06/17/2013.	Minor Damage
Manufacturer Recall No open recalls reported to CARFAX. View Toyota disclosure	No Recalls Reported
Basic Warranty No data reported to CARFAX.	No Data Reported

CARFAX Title History	Summary
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	No Problem


CARFAX Detailed History

Date	Mileage	Source	Comments
06/15/1985		NICB	Vehicle manufactured and shipped to original dealer
04/01/1992	68,487	Idaho Motor Vehicle Dept. Rupert, ID	Odometer reading reported
04/15/1992		Idaho Motor Vehicle Dept. Rupert, ID	Title issued or updated
04/16/2007	234,992	Texas Inspection Station El Paso, TX	Passed safety inspection - Passed emissions inspection
04/26/2007		Texas Motor Vehicle Dept.	Title issued or updated - New owner reported

		El Paso, TX		
06/21/2007	235,024	Casa Ford Lincoln El Paso, TX 915-779-2272 casaford.com ★ 4.6 / 5.0 861 Verified Reviews ♥ 9,090 Customer Favorites	*	Vehicle serviced - Rear shock absorber(s) replaced - Shock absorber(s) replaced - Steering damper replaced - Thrust angle alignment performed - Vehicle washed/detailed
08/16/2007	237,173	A N W Automotive El Paso, TX 915-595-2778	*	Vehicle serviced - Fluids checked - Oil and filter changed - Tune-up performed
05/02/2008	242,774	Texas Inspection Station El Paso, TX		Failed emissions inspection
05/02/2008		Casa Ford Lincoln El Paso, TX 915-779-2272 casaford.com ★ 4.6 / 5.0 861 Verified Reviews ♥ 9,090 Customer Favorites	×	Vehicle serviced - Emissions inspection performed - Emissions or safety inspection performed - Safety inspection performed
05/02/2008	242,790	Texas Inspection Station El Paso, TX		Passed emissions inspection
07/10/2008	243,902	A N W Automotive El Paso, TX 915-595-2778	*	Vehicle serviced - Brakes checked - Clutch slave cylinder replaced - Differential fluid flushed/changed - Differential serviced - Fluids checked
07/28/2008	243,922	Casa Ford Lincoln El Paso, TX 915-779-2272 casaford.com ★ 4.6 / 5.0 861 Verified Reviews Customer Favorites	*	Vehicle serviced
08/19/2008	244,168	A N W Automotive El Paso, TX 915-595-2778	×	Vehicle serviced - Brakes checked - Oil and filter changed

		★ 5.0 / 5.0107 Verified Reviews★ 12 Customer Favorites		
03/12/2009	245,216	A N W Automotive El Paso, TX 915-595-2778 ★ 5.0 / 5.0 107 Verified Reviews ● 12 Customer Favorites	*	Vehicle serviced - Fluids checked - Interior lights checked - Lights checked - Oil and filter changed
06/02/2009	245,987	Texas Inspection Station El Paso, TX		Failed emissions inspection
06/02/2009	245,997	Texas Inspection Station El Paso, TX		Passed emissions inspection
06/09/2009		Casa Ford Lincoln El Paso, TX 915-779-2272 casaford.com ★ 4.6 / 5.0 861 Verified Reviews ♥ 9,090 Customer Favorites	*	Vehicle serviced - Emissions inspection performed - Emissions or safety inspection performed - Safety inspection performed
09/01/2009	247,834	A N W Automotive El Paso, TX 915-595-2778 ★ 5.0 / 5.0 107 Verified Reviews 12 Customer Favorites	*	Vehicle serviced - Brakes checked - Brake master cylinder replaced/repaired - Oil and filter changed
02/02/2010	251,316	A N W Automotive El Paso, TX 915-595-2778 ★ 5.0 / 5.0 107 Verified Reviews ● 12 Customer Favorites	*	Vehicle serviced - Oil and filter changed
04/20/2010		Texas Motor Vehicle Dept. El Paso, TX		Registration issued or renewed - Passed safety inspection
04/29/2010	253,169	A N W Automotive El Paso, TX 915-595-2778 ★ 5.0 / 5.0 107 Verified Reviews	*	Vehicle serviced - Clutch master cylinder replaced - Clutch slave cylinder replaced - Oil and filter changed

		12 Customer Favorites		
04/01/2011		Texas Motor Vehicle Dept. El Paso, TX		Registration issued or renewed - Passed safety inspection
05/12/2011	255,458	A N W Automotive El Paso, TX 915-595-2778	*	Vehicle serviced - Interior lights checked - Oil and filter changed
11/25/2011	255,687	Casa Ford Lincoln El Paso, TX 915-779-2272 casaford.com ★ 4.6 / 5.0 861 Verified Reviews ♥ 9,090 Customer Favorites	*	Vehicle serviced - Battery/charging system checked - Battery replaced
12/27/2011	255,727	A N W Automotive El Paso, TX 915-595-2778 ★ 5.0 / 5.0 107 Verified Reviews ● 12 Customer Favorites	*	Vehicle serviced - Maintenance inspection completed - Horn contact replaced
04/01/2012		Texas Motor Vehicle Dept. El Paso, TX		Registration issued or renewed - Passed safety inspection
07/03/2012	256,189	A N W Automotive El Paso, TX 915-595-2778 ★ 5.0 / 5.0 107 Verified Reviews ● 12 Customer Favorites	*	Vehicle serviced - Antifreeze/coolant flushed/changed - Brake pedal pad replaced - Brakes serviced - Clutch pedal pad replaced - Tire condition and pressure checked
08/09/2012	256,477	A N W Automotive El Paso, TX 915-595-2778 ★ 5.0 / 5.0 107 Verified Reviews ● 12 Customer Favorites	*	Vehicle serviced - Clutch pressure plate replaced - Clutch replaced - Oil and filter changed
02/12/2013	257,201	A N W Automotive El Paso, TX 915-595-2778 ★ 5.0 / 5.0 107 Verified Reviews	×	Vehicle serviced - Exhaust system checked - Oil and filter changed






- Damage to left front

- Airbags did not deploy







Minor damage is usually cosmetic, including dents or scratches to the vehicle body.

09/30/2013 258,097

Martin Tire Company El Paso, TX 915-592-6496 martintire.com/



4.8 / 5.0

213 Verified Reviews



74 Customer Favorites



Vehicle serviced

- Alignment performed

10/01/2013

A N W Automotive El Paso, TX 915-595-2778




5.0 / 5.0

107 Verified Reviews



Vehicle serviced

- Air filter replaced
- Fluids checked
- Front shock absorber(s) replaced
- -Oil and filter changed
- Rear shock absorber(s) replaced



10/15/2014 A & W Automotive Vehicle serviced - Emissions or safety inspection El Paso, TX 915-595-2778 performed **5.0 / 5.0** 107 Verified Reviews **12** Customer Favorites 03/02/2015 260,114 Martin Tire Company Vehicle serviced - Tire(s) balanced El Paso, TX 915-532-6519 - Tires rotated martintire.com **4.6 / 5.0** 34 Verified Reviews 03/10/2015 260,150 A & W Automotive Vehicle serviced El Paso, TX - Maintenance inspection completed 915-595-2778 - Air filter checked - Body lubricated **5.0 / 5.0** - Cooling system hose(s) replaced 107 Verified Reviews - Drivability/performance checked **12** Customer Favorites - Fluids checked - Emissions or safety inspection performed - Lower radiator hose replaced - Oil and filter changed - Radiator cap replaced - Tire condition and pressure checked 04/01/2015 Texas Registration issued or renewed Motor Vehicle Dept. - Passed safety inspection El Paso, TX 04/12/2016 262,017 A & W Automotive Vehicle serviced - Maintenance inspection completed El Paso, TX 915-595-2778 - Air filter checked -Battery/charging system checked **5.0 / 5.0** - Battery replaced 107 Verified Reviews - Body lubricated **12** Customer Favorites - Drivability/performance checked - Fluids checked - Emissions or safety inspection performed - Oil and filter changed - Tire condition and pressure checked 05/02/2016 Registration issued or renewed Texas Motor Vehicle Dept. - Passed safety inspection El Paso, TX Vehicle serviced 08/01/2017 262,155 A & W Automotive El Paso, TX - Maintenance inspection completed 915-595-2778 - A/C refrigerant recharged - Air filter checked **5.0 / 5.0** - Body lubricated 107 Verified Reviews

		12 Customer Favorites		 - Drivability/performance checked - Fluids checked - Emissions or safety inspection performed - Oil and filter changed - Radiator checked - Thermostat replaced - Tire condition and pressure checked
08/01/2017		Texas Motor Vehicle Dept. El Paso, TX		Registration issued or renewed - Passed safety inspection - Vehicle color noted as Blue
08/01/2018		Texas Motor Vehicle Dept. El Paso, TX		Registration issued or renewed - Passed safety inspection - Vehicle color noted as Blue
09/03/2019	263,113	Martin Tire Company El Paso, TX 915-532-6519 martintire.com ★ 4.6 / 5.0 34 Verified Reviews	×	Vehicle serviced - Tire(s) replaced - Tires rotated
09/04/2019		A & W Automotive El Paso, TX 915-595-2778 ★ 5.0 / 5.0 107 Verified Reviews 12 Customer Favorites	*	Vehicle serviced - Maintenance inspection completed - Air filter checked - Body lubricated - Brakes checked - Drivability/performance checked - Fluids checked - Emissions or safety inspection performed - Oil and filter changed - Tire condition and pressure checked
09/24/2019		Texas Motor Vehicle Dept. El Paso, TX		Registration issued or renewed - Passed safety inspection - Vehicle color noted as Blue
08/11/2020	263,386	A & W Automotive El Paso, TX 915-595-2778 ★ 5.0 / 5.0 107 Verified Reviews 12 Customer Favorites	*	Vehicle serviced - Maintenance inspection completed - Air filter checked - Body lubricated - Brakes checked - Drivability/performance checked - Fluids checked - Emissions or safety inspection performed - Oil and filter changed - Tire condition and pressure checked
09/01/2020		Texas Motor Vehicle Dept. El Paso, TX		Registration issued or renewed - Passed safety inspection - Vehicle color noted as Blue

09/27/2021	263,519	A & W Automotive El Paso, TX 915-595-2778 ★ 5.0 / 5.0 107 Verified Reviews ■ 12 Customer Favorites	*	Vehicle serviced - Maintenance inspection completed - A/C refrigerant recharged - A/C system serviced - Air filter checked - Body lubricated - Brakes checked - Drivability/performance checked - Drive belts checked - Fluids checked - Emissions or safety inspection performed - Oil and filter changed - Tire condition and pressure checked
10/18/2021		Texas Motor Vehicle Dept. El Paso, TX		Registration issued or renewed - Passed safety inspection - Vehicle color noted as Blue
08/29/2022	263,678	A & W Automotive El Paso, TX 915-595-2778 ★ 5.0 / 5.0 107 Verified Reviews ■ 12 Customer Favorites	*	Vehicle serviced - Maintenance inspection completed - Air filter checked - Body lubricated - Brakes checked - Drivability/performance checked - Fluids checked - Emissions or safety inspection performed - Oil and filter changed - Tire condition and pressure checked
09/01/2022		Texas Motor Vehicle Dept. El Paso, TX		Registration issued or renewed - Passed safety inspection - Vehicle color noted as Blue
02/15/2025	263,789	Online Listing		Vehicle offered for sale
04/04/2025	263,790	Online Listing		Vehicle offered for sale
05/23/2025		Online Listing		Vehicle offered for sale
08/08/2025		Bravo Cadillac of El Paso El Paso, TX 915-778-6633 bravoelpaso.com/ 4.5 / 5.0 248 Verified Reviews Customer Favorites		Vehicle sold
08/21/2025		Arizona Motor Vehicle Dept. Mesa, AZ		Title issued or updated - Dealer took title of this vehicle while it was in inventory

11/22/2025 263,809 Canyon State Classics

LLC Mesa, AZ 480-703-2337

canyonstateclassics.com

/about-us + 4.8 / 5.0

6 Verified Reviews

11/24/2025 CARFAX Car Care

Manufacturer Recommended Maintenance Schedules

Vehicle offered for sale



Get this vehicle's maintenance schedule, service history and recall alerts at carfax.com/service.

Have Questions? Please visit our Help Center at www.carfax.com.

CARFAX Glossary

Accident Indicator

CARFAX receives information about accidents in all 50 states, the District of Columbia and Canada.

Not every accident is reported to CARFAX. As details about the accident become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- According to the National Safety Council, Injury Facts, 2021 edition, 5% of the 276 million registered vehicles in the U.S. were involved in an accident in 2019. Over 77% of these were considered minor or moderate.
- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 11/24/25 at 7:02:23 AM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Damage Severity

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

Failed Emissions Inspection

The emissions check performed during a vehicle inspection indicated the vehicle was emitting more than allowable emissions standards and/or had missing or modified parts. Repeated failed emissions records can indicate engine problems and CARFAX recommends you have the vehicle inspected.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Toyota Recall / Service Campaign

Portions of this report have been included under license from Toyota Motor North America, Inc. ("TOYOTA"), License Agreement TMS1013. This data applies only to vehicle marketed or originally sold in Mexico and the United States of America, including Guam, Saipan, American Samoa, Puerto Rico, the U.S. Virgin Islands and the other United States territories and protectorates with currently open safety or emissions recalls, or service campaigns. While TOYOTA provides data to Carfax Inc. on a regular basis, this report may not include very recent activity. For the manufacturer's most current information on recall/campaign activity for any Toyota, Lexus or Scion brand vehicle, you must go to http://toyota.com/recall or http://lexus.com/recall.

Follow Us:



facebook.com/CARFAX



@CARFAXinc



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

SYSTEMATIC RETRIEVAL OF THE CONTENT OR OTHER DATA FROM THIS SITE TO CREATE OR COMPILE, DIRECTLY OR INDIRECTLY, IN WHOLE OR IN PART, A COLLECTION, COMPILATION, DATABASE OR DIRECTORY WITHOUT THE EXPRESS WRITTEN PERMISSION OF CARFAX IS STRICTLY PROHIBITED. BY USING THE CARFAX VEHICLE HISTORY REPORT YOU AGREE TO THE CARFAX TERMS OF USE AND PRIVACY STATEMENT.

© 2025 CARFAX, Inc., part of S&P Global. All rights reserved. 11/24/25 7:02:23 AM (CST)